


## Customer Showcase

CS140- Wayne Frederick

**Background:** These pictures show the adapters to the collet chuck and also for the 3 and 4 jaw chucks. The one plate is bolted onto the spindle and stays there. The collet chuck is bolted to that adapter directly, and all others use a second adapter to mount for each of the 3 and 4 jaw chucks. I used the bolt pattern for the collet chuck but it was too close to the other chucks so I put in a second hole pattern for bolting on the 3 and 4 jaw chucks.







# Customer Showcase

---